

Remediation Plan

School: Greenville Elementary

At Greenville Elementary, a total number of 101 fixtures were tested. Three fixtures did present lead levels that exceed the EPA's action level. The action level of 15 ppb is not a measure of health effects. It serves as a signal to the facility to take steps to reduce lead in the water.

We have taken one or more of the following actions to address this situation:

- Shut off the water to these fixtures;
- Installed signs where applicable indicating these fixtures are for hand-washing only;
- Replaced the fixtures.

The following actions were taken for each fixture (in chronological order):

- **Fixtures 108 & 144**

- The fixture was taken offline on 3/15/2023.
- “Do Not Use” signs were posted on 3/15/2023.
- The fixture was replaced on 3/29/2023.
- The new fixture was retested on 4/12/2023.
- The N.A.F.C.S. Corporation received the results on 4/27/2023. The samples tested were non-detect and the resumption of this fixture may go into effect immediately.

- **Fixture 143**

- The fixture was taken offline on 3/15/2023.
- “Do Not Use” signs were posted on 3/15/2023.
- The fixture was removed completely on 3/29/2023 (will never be used again).