Remediation Plan

School: Scribner Middle School

At Scribner Middle School, a total number of 180 fixtures were tested. Five fixtures did

present lead levels that exceed the EPA's action level. The action level of 15 ppb is not

a measure of health effects. It serves as a signal to the facility to take steps to reduce

lead in the water.

We have taken one or more of the following actions to address this situation:

• Shut off the water to these fixtures;

• Installed signs where applicable indicating these fixtures are for hand-washing

only;

Replaced the fixtures.

The following actions were taken for each fixture (in chronological order):

Fixtures 170, 180, 259, & 274

- The fixture was taken offline on 5/2/2023.
- o "Do Not Use" signs were posted on 5/2/2023.
- o The fixture was replaced on 5/19/2023.
- The new fixture was retested on 5/23/2023.
- The N.A.F.C.S. Corporation received the results on 6/8/2023. The samples tested were non-detect and the resumption of this fixture may go into effect immediately.

Fixture 176

- The fixture was taken offline on 5/2/2023.
- "Do Not Use" signs were posted on 5/2/2023.
- The fixture was replaced on 5/19/2023.
- The new fixture was retested on 5/23/2023.
- The N.A.F.C.S. Corporation received the results on 6/8/2023. The samples tested did present lead levels that exceed the EPA's action level.
 The resumption of this fixture may <u>not</u> go into effect.
- The water shut off was changed on 6/9/2023.
- The fixture was retested again on 6/27/2023.
- The N.A.F.C.S. Corporation received the results on 7/13/2023. The samples tested were non-detect and the resumption of this fixture may go into effect immediately.